



Application Selection Guide

GenSwiss Signature Series Saw Arbors

YES 	NO 
When using a slitting saw, 2 to 3 teeth cutting in the material with the proper feedrate is ideal.	You do not want to have too many teeth engaging the workpiece. There will be chip clearing issues. Not having enough teeth on the work piece will cause vibration and will add premature wear to the saw blade.

